

Occupational Safety Program

Asbestos Management

Inventory

Known Locations of Asbestos at TU (as of May 28, 2025)

Г	
Administration Building	Vinyl floor tile/mastic (under carpet)
(7720 York Road) (1957)	Black tar pipe coating
	Fittings in walls/above plaster ceilings
Armory (1932)	Vinyl floor tile/mastic in basement
	Silver roof flashing (applied on grey metal flashing)
Auburn House (1790)	Fire doors
Barnes Hall (2016)	No asbestos detected
Barton House (2011)	No asbestos detected
Burdick Hall (1968)	Vinyl floor tile (under carpet, new tiles & including
	under hallway floor tiles)
	Fire doors
	Fittings (above plaster ceilings/in walls)
	Transite panels (building perimeter)
	Black tar pipe/duct coating
	Exterior overhang – plaster
Center For the Arts (1973)	Vinyl floor tile/mastic
	Fire doors
	Fittings (above ceiling tile/in walls)
Child Care Center (2007)	No asbestos detected
College of Health Professions Building	No asbestos detected
(2024)	
College of Liberal Arts Building (2011)	No asbestos detected
Cook Library (1969)	Vinyl floor tile/mastic (including under carpet)
	Fire doors
	Fittings (above ceiling tile/in walls)
	Exterior overhang – plaster
Douglass House (2011)	No asbestos detected
Enrollment Services (1972)	Fire doors
	Vinyl floor tile/mastic (including under carpet &
	hallway floor tile)
	Fittings (enclosed in walls)
General Services (1970)	Fire doors
	Fittings (above ceiling tile/in walls)
	Vinyl floor tile/mastic
Glen Complex	Fire doors
Towers A, B, C, & D (1983)	
	•

Towson University Department of Environmental Health & Safety (EHS)

Phone: 410-704-2949 Fax: 410-704-2993 Emergency: 911 Email: <u>safety@towson.edu</u> TUPD: 410-704-4444

Website: https://www.towson.edu/public-safety/environmental-health-safety/

Glen Dining Hall (1983)	Fire doors
Harris Hall (2008)	No asbestos detected
Hawkins Hall (1977)	Fire doors
	Vinyl floor tile/mastic
	Transite in floor (heating duct)
	Outside light fixture insulation pads
	Chalk board glue dots
	Roof drain mastic by pipe penetration to roof
Health & Counseling Centers	Fire doors
(Ward Hall) (1951)	Fittings (In walls/crawl space)
	NOTE-Crawl space: soil encapsulated-do not
	disturb by penetrating ground
Health & Counseling Centers	Fire doors
(West Hall) (1951)	Fittings (in walls/crawl space)
	NOTE-Crawl space: soil encapsulated-do not
	disturb by penetrating ground
John B. Schuerholz Park (2001)	No asbestos detected
Johnny Unitas ® Stadium (1977)	No asbestos detected
Landscape Services (2001)	No asbestos detected
Lecture Hall (1977)	Fire doors
	Floor tile/mastic
	Roof flashing
Linthicum Hall (1968)	Vinyl floor tile/mastic (including under hallway
	floor tiles)
	Fittings (except mechanical room)
	Transite panels in mechanical
	room/walls/perimeter
	Offices
	Black mastic: behind white/caulk Boards; pipe
	Covering inside walls
Marshall Hall (2016)	No asbestos detected
Media Center (1957)	Vinyl floor tile/mastic (mainly under carpet)
	Fire doors
	Fittings (except ground floor mechanical/
	electrical rooms)
	Fittings/pipes (enclosed in walls/floors)
Millennium Hall (2000)	
Millennium Hall (2000)	No asbestos detected
Newell Dining Hall (1914)	No asbestos detected Fire doors Fittings (in walls and ceilings)

	Insulation Rope - 12" water line
Newell Hall (1914)	Fire doors Fittings (in walls & in crawl space) Fireproofing (NW Third Floor Bathroom-behind wall)
Power Plant (1914)	Fire doors
Prettyman Hall (1957)	Fire doors Fittings (above ceilings/in walls) Vinyl floor tile/mastic (under carpet RA/RLC room)
Psychology Building (1977)	Vinyl floor tile/mastic Fire doors Outside light fixture insulation pads Heating duct fittings Transite in floor (heating duct)
Public Safety Building (2013)	No asbestos detected
Residences at 10 West Burke Avenue (1984)	No asbestos detected
Residence Tower (1972)	Ducts (mechanical room floors) Acoustical spray (in ceiling fixtures-lights, conduit)
Richmond Hall (1923)	Fire Doors Fittings (in walls & crawl space) Vinyl floor tile/mastic
Scarborough Hall (1964)	Fire doors Fittings Vinyl floor tile/mastic (basement storage rooms) Vinyl floor tile/mastic
Science Complex (2021)	No asbestos detected
Smith Hall (1964, 1976)	Fire doors Fittings (above ceiling tile, under sinks, in walls) NOTE: New Smith Hall only-fittings are non-ACM) Transite panel-cabinets/hoods Epoxy floor with black mastic Floor tile/mastic Epoxy floor with black mastic
Stephens Hall (1914)	Fittings/pipe insulation (enclosed in walls/floor)
SECU Arena (TU Arena) (2013)	No asbestos detected

Floor tile and mastic Metal duct caulk Pipe fitting end cap encapsulate Black mastic-behind mirrors/boards Towson Run (1989) No asbestos detected TUNE (2013) No asbestos detected University Union (1972) Fire doors Spray on fireproofing: Behind/above ducts in ceilings Debris in walls/columns, Above blockwalls Elevator Room (above plaster) Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected 7800 York Road (1962) Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings	T 0 1 (10==)	
Metal duct caulk Pipe fitting end cap encapsulate Black mastic-behind mirrors/boards Towson Run (1989) No asbestos detected TUNE (2013) No asbestos detected Tubman House (2008) No asbestos detected University Union (1972) Fire doors Spray on fireproofing: Behind/above ducts in ceilings Debris in walls/columns, Above blockwalls Elevator Room (above plaster) Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected 7800 York Road (1962) Van Bokkelen Hall (1962) Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings	Towson Center (1977)	Fire doors
Pipe fitting end cap encapsulate Black mastic-behind mirrors/boards Towson Run (1989) No asbestos detected TUNE (2013) No asbestos detected Tubman House (2008) No asbestos detected University Union (1972) Fire doors Spray on fireproofing: Behind/above ducts in ceilings Debris in walls/columns, Above blockwalls Elevator Room (above plaster) Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected 7800 York Road (1962) Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		
Towson Run (1989) No asbestos detected TUNE (2013) No asbestos detected Tubman House (2008) No asbestos detected University Union (1972) Fire doors Spray on fireproofing: Behind/above ducts in ceilings Debris in walls/columns, Above blockwalls Elevator Room (above plaster) Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		
TOWSON Run (1989) TUNE (2013) No asbestos detected Tubman House (2008) No asbestos detected Tibman House (2008) No asbestos detected Fire doors Spray on fireproofing: Behind/above ducts in ceilings Debris in walls/columns, Above blockwalls Elevator Room (above plaster) Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected 7800 York Road (1962) Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Pipe fitting end cap encapsulate
TUNE (2013) No asbestos detected Tubman House (2008) No asbestos detected Fire doors Spray on fireproofing: Behind/above ducts in ceilings Debris in walls/columns, Above blockwalls Elevator Room (above plaster) Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected 7800 York Road (1962) Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Black mastic-behind mirrors/boards
Tubman House (2008) University Union (1972) Fire doors Spray on fireproofing: Behind/above ducts in ceilings Debris in walls/columns, Above blockwalls Elevator Room (above plaster) Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceilling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings	Towson Run (1989)	No asbestos detected
University Union (1972) Fire doors Spray on fireproofing: Behind/above ducts in ceilings Debris in walls/columns, Above blockwalls Elevator Room (above plaster) Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected 7800 York Road (1962) Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings	TUNE (2013)	No asbestos detected
Spray on fireproofing: Behind/above ducts in ceilings Debris in walls/columns, Above blockwalls Elevator Room (above plaster) Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings	Tubman House (2008)	No asbestos detected
Behind/above ducts in ceilings Debris in walls/columns, Above blockwalls Elevator Room (above plaster) Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected 5pray-on fire proofing Vinyl floor tile/mastic Pipe fittings	University Union (1972)	Fire doors
Debris in walls/columns, Above blockwalls Elevator Room (above plaster) Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Spray on fireproofing:
Above blockwalls Elevator Room (above plaster) Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Behind/above ducts in ceilings
Elevator Room (above plaster) Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Debris in walls/columns,
Fittings (1st, 2nd, 3rd floors [enclosed in walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic — red West Village Commons (2011) No asbestos detected 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Above blockwalls
walls/tunnel]) Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected 7800 York Road (1962) Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Elevator Room (above plaster)
Floor tile and mastic Steam pipe gaskets-Room 129 Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Fittings (1st, 2nd, 3rd floors [enclosed in
Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		walls/tunnel])
Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Floor tile and mastic
Van Bokkelen Hall (1932) Fire doors Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Steam pipe gaskets-Room 129
Fittings/debris (basement crawl space) Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings	Van Bokkelen Hall (1932)	
Floor tile/mastic (First floor lobby area) Stairwell tread/mastic – red West Village Commons (2011) No asbestos detected Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Fittings/debris (basement crawl space)
West Village Commons (2011) 401 Washington Ave (1970) Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Floor tile/mastic (First floor lobby area)
West Village Commons (2011) No asbestos detected Fire doors Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		, , , , , , , , , , , , , , , , , , , ,
Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings	West Village Commons (2011)	·
Pipe insulation and fittings in mechanical rooms Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		
Vinyl floor tile/mastic Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings	401 Washington Ave (1970)	Fire doors
Roof flashing Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Pipe insulation and fittings in mechanical rooms
Lobby plaster ceiling Fittings 7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Vinyl floor tile/mastic
7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Roof flashing
7400 York Road (Renovated 2014) No asbestos detected Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Lobby plaster ceiling
7800 York Road (1962) Spray-on fire proofing Vinyl floor tile/mastic Pipe fittings		Fittings
Vinyl floor tile/mastic Pipe fittings	7400 York Road (Renovated 2014)	No asbestos detected
Pipe fittings	7800 York Road (1962)	Spray-on fire proofing
		Vinyl floor tile/mastic
		Pipe fittings
black tal pipe/dact coating		Black tar pipe/duct coating

NOTE: Many of these buildings contain vinyl floor tile/mastic, sheetrock/spackle and mastic behind caulk/white boards or mirrors, or coating on pipes/pipe fittings, which may contain asbestos. The State provided survey did not include bulk sampling or analysis of these for asbestos content. This portion of the survey is being accomplished through the University's resources (case by case basis) and results, when available, shall be added to the list of known locations of asbestos. Until this can be accomplished, all vinyl floor tile/mastic, sheetrock/spackle and mastic shall be presumed asbestos containing materials (PACM) and proper precautions taken. If maintenance

work is required which involves disturbing any of these items, please consult Environmental Health & Safety 410-704-2949 prior to performing work.

This list, by building, is intended to be a guidance document only. It is substantially complete; however, the intent is to inform and alert personnel to the known locations of asbestos containing materials and thereby avoid accidental disturbance of the material and reduce the potential for fiber release episodes.